
12.0 SOUR FACILITY GUIDELINES

When working around any sour facilities, follow the guidelines in the Shell "Survey Operations Safety Manual" which reads as follows:

- All supervisory personnel shall report to the complex superintendent and discuss the work schedule for each phase of the operation.
- Survey personnel shall be given an on-site orientation by operation plant/field personnel and advised of any plant or field activities that may conflict with the survey operation.
- Survey personnel shall exchange radio/mobile frequencies with plant or field facilities so that communication lines are readily available. Contact numbers and frequencies shall be posted at all radios/mobiles.
- Two self-contained breathing apparatus (SCBA) shall be located in strategic locations.
- All survey personnel shall possess valid H₂S Alive or equivalent certificates and valid first aid tickets.
- All survey personnel shall be clean- (i.e. no beards, van dykes, goatees or Manchuria).
- All survey personnel shall have collar length hair; if longer hair must be tied back.
- All survey personnel shall wear fire-retardant coveralls based on hazard assessment.
- All survey personnel shall wear high-visibility vests and hard hats when working on plant and field roadways.
- Appropriate signage shall be used when crew is working on or near plant or field roadways.

**BEIRSTO LEHNERS KETCHUM
ENGINEERING LTD.**

JULY 2007